Bruhath Bangalore Mahanagara palike,		
Inspection Report		
1	Name of work	Providing Ornamental Grill and improvement at J P Park in Ward No.17
2	Administration Approval & Date	JC/RRN/AS/2933/2013-14 Dtd.1-03-2014 by JC RRNZ
3	Technical Sanction Estimate No.& Date	EE(P)/RRN/TS/58/13-14 dtd:1-03-2014 by EE(P) (RRN)
4	Estimate Amount	Rs.15.00 Lakhs
5	Job Code No.	017-14-000114
6	P-Code	P -0190
7	Agreement No & date	EE/RRN/Proj/AG No./122/2013-14 Dtd.4-03-2014
8	Work order Number & Date	EE/Proj/RRN/W.O/122/2013-14 Dtd.4-03-2014
9	Contract Amount as per Agreement	Rs. 15,00,000/- + KRIDL Charges
10	Bill Amount	Rs.14,43988/- including KRIDL Charges
11	B.R. No. & Date	190/2014-15 dt.30-07-2014
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	2267/14-15 Pages 226601 to 226603/1
14	Date of Inspection	3/9/2015
15	Enclosures	1) Extract of MB No.2267 Page No.226603/1 2) 3 Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me along with the Concerned persons. The measurements of the Items have been checked by me and found to be Satisfactory

As per level is required for 2.0 mtrs depth

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು (ಯೋಜನೆ)
EE (P) RR Nagara
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಲಯ

3/9/2015
(R.Sathyanarayana)
Inspection Report officer,